

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID	X	YW		Transfer		Compost		SLAS		COUNTY: VANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		PERMIT NO.: N1033
CDLF		Tire T&P / Collection		Tire Monofill	1 1	ndustrial Landfill		DEMO		SDTF		FILE TYPE: COMPLIANCE

Date of Site Inspection: January 30, 2012 Date of Last Inspection: September, 2009 (pre-op)

FACILITY NAME AND ADDRESS:

Riverside Farm

4920 Charlie Grissom Road

Kittrell, NC 27544

GPS COORDINATES: N: <u>36.18105</u> E: <u>78.50328</u>

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Thomas Alls

Telephone: 919-971-0471

Email address: tomalls@yahoo.com

Fax: 919-528-7766

FACILITY CONTACT ADDRESS:

Thomas Alls

1434 Mt. Olive Church Road Franklinton, NC 27525

PARTICIPANTS:

Mary Whaley, NCDENR, Solid Waste Section

STATUS OF PERMIT:

LCID Notification issued October 13, 2009. Site is recorded in Book 1204 Pages 0427, Vance County.

PURPOSE OF SITE VISIT:

Comprehensive Audit

STATUS OF PAST NOTED VIOLATIONS:

NA

OBSERVED VIOLATIONS

NA

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS:

- 1. The site is not being used as an LCID at this time.
- 2. Insure that no part of the Notified LCID is in the 100 year flood zone.
- 3. There needs to be clearly visible markers showing where the less than two acre area of waste is located.
- 4. It is strongly recommended that a minimum of 25 feet is made available around the site as an emergency vehicle access road in case of fire.
- 5. The concrete that is going to be used as road base must not be stored at the LCID site or within the 100 foot buffers of the LCID. If it is determined that the concrete is not going to be used as road base and it is going to go in the LCID, it also must be covered with soil within 30 days of receipt.
- 6. There is to be no treated wood in the LCID. There are, what appeared to be, railroad ties on the pile of concrete. If these ties are to be used, then they need to be stored away from the LCID including the 100 foot buffers. If the ties are to be disposed of, they must be disposed of at a permitted site that can accept them. They must not be disposed of in the LCID.

Phone: 919-693-5023

Please contact me if you have any questions or concerns regarding this inspection report.

Environmental Senior Specialist

Regional Representative

Muhaly

Sent on: February 9, 2012	X Email		Hand delivery		X	US Mail	Certified No. [_]

Copies: Dennis Shackelford, Eastern District Supervisor Shawn McKee, Compliance Officer





Covered LCID with ground cover established